

## Clash Publish

Clash Computation Specification			
Products Selected		Value	Status
AT612302MQ – BOC Rail Feet, SECTOR 13	NMC_0019 - FOOT B WITH BRACKET HOLES - MAIN BOLTS AND WELDINGS	53.3 mm	Relevant
	NH_0001 - HF TRUCK IN ACCESS POSITION SIDE C	-51 mm	Relevant
	VHB_0001 - CENTRAL PAIR OF FEET B *	2 mm	Relevant
	VHB_0008 - FOOT B WITH BRACKET HOLES **	7 mm	Relevant
	VHB_0002 - STANDARD PAIR OF FEET A1 (C1) ***	2 mm	Relevant

<sup>\*</sup> This conflict exists for all Feet on both side US15 and USA15

<sup>\*\*</sup> Conflict exists for all Feet everywhere with washer on both side US15 and USA15

<sup>\*\*\*</sup> Conflict exists for all Feet on both side US15 and USA15 except of end feet. Conflict similar to clash with VHB\_0001


**AT612302MQ –** BOC Rail Feet, SECTOR 13

NMC\_0019 - FOOT B WITH BRACKET HOLES - MAIN BOLTS AND WELDINGS

Clash

-53.3 mm

Relevant




**AT612302MQ –** BOC Rail Feet, SECTOR 13


NH\_0001 - HF TRUCK IN ACCESS POSITION SIDE C

Clash

51mm


Relevant






SIDE C, Sector 13


Be careful with cut-out dimensions, while this is prototype !!!



AT612302MQ - BOC Rail Feet, SECTOR 13 VHB\_0001 - CENTRAL PAIR OF FEET B Clash -2 mm Relevant



## Clash View:




**AT612302MQ –** BOC Rail Feet, SECTOR 13


VHB\_0008 - FOOT B WITH BRACKET HOLES


Clash

-7 mm

Relevant







Clash value: ~ 7 mm

SIDE C, Sector 13

Clash exists everywhere with washer

**AT612302MQ –** BOC Rail Feet, SECTOR 13

VHB\_0002 - STANDARD PAIR OF FEET A1 (C1)

Clash

-2 mm

Relevant

